



Southern Geoscience Consultants Pty Ltd ACN 067 552 461
Level 1, 183 Great Eastern Highway, Belmont WA 6104 AUSTRALIA
PO Box 694, Belmont WA 6984 AUSTRALIA
T +61 (8) 6254 5000 F +61 (8) 6254 5099
E geophysics@sgc.com.au W www.sgc.com.au

SOUTHERN GEOSCIENCE
CONSULTANTS

MEMORANDUM

TO	Finn Barrett
FROM	Paul Mutton
DATE	21/3/2012
RE	Smithton Magnetic Modelling - Preliminary

Finn,

Below are some notes on the magnetic anomalies adjacent and coincident with the drill holes planned at Smithton.

1 MT FRANKLAND – MONTAGUE RIVER

1. Magnetic Anomaly description : Location appears to be a fault disrupting a long magnetic unit (Figure 1)
2. Signs of Remanence: Yes. Significant low to NW of magnetic anomaly indicates strong remanence present
3. Model (potent): Not completed. Remanence is too strong.
4. Strike & strike direction: NE-SW
5. Dip & Dip Direction: Unknown
6. Depth to source:
7. Analytic Signal Image Check:
8. Any adjustment from currently planned hole required: An adjustment is required if the target is the magnetic unit. It is unclear as to what is being targeted here. Figure 2 shows the google earth photography with the overlain Analytic Signal image




Figure 1 TMI image on left and Analytic Signal on Right




Figure 2 Google earth image with Analytic signal overlay

2 MT FRANKLAND – BLACKWATER SPUR 8

1. Magnetic Anomaly description : North end of a 2km long discrete magnetic anomaly (Figure 3)
2. Signs of Remanence: Looks like little remanence as Analytic Signal image matches TMI image very well (Figure 3)

3. Model (potent): Completed
4. Strike: 155
5. Dip & Dip Direction: 70 degrees towards 065
6. Depth to source: 40m
7. Analytic Signal Image Check: Coincident
8. Adjustment from currently planned hole: Move E about 80m and drill to SE
le Collar 324510E, 5437060N dipping 70 degrees towards 240. This is very close to the road. Collar
could also be move to the SW along the road if necessary. The road pretty much follows the
magnetic anomaly (Figure 4).




Figure 3 TMI image on left and Analytic Signal on Right




Figure 4 Google earth image with Analytic signal overlay. New hole collar marked with a star




Figure 5 Data with model fit (above) and recommended drill hole in model (below)

3 3 MILE HILL

1. Magnetic Anomaly description : Discrete magnetic high
2. Signs of Remanence: The RTP1VD matches the Analytic Signal quite well (Figure 6) indicating that remanence is minor, however there is a distinct magnetic low on the west side of the anomalies indicating that some remanence is present (Figure 6 and Figure 7).
3. Model (potent): Modelling was attempted however the remanence present and complex anomaly with the superimposed response of multiple conductors (Figure 7) creates models with high uncertainty.
4. Strike: 160
5. Dip & Dip Direction: unknown
6. Depth to source: 100-120m?
7. Analytic Signal Image Check:
8. Adjustment from currently planned hole required: The best targeting strategy is to target the centre of the analytic signal anomaly with a vertical hole. This is at 319800E, 5461440N. This is only 60m from the northern planned drill hole.




Figure 6 TMI image on left, Analytic Signal Image in Centre and RTP1VD on right. The close correlation between RTP and Ansig images indicates remanence is minor although there is some indication of remanence affecting the anomaly in the SW




Figure 7 Data (blue) with model fit (black) showing poor fit due to complex anomaly with remanent magnetism present.

4 DUNNS

1. Magnetic Anomaly description :
2. Signs of Remanence:
3. Model (potent): Not completed
4. Strike & strike direction:
5. Dip & Dip Direction:
6. Depth to source:
7. Analytic Signal Image Check:
8. Any adjustment from currently planned hole required

5 MONTAGU

1. Magnetic Anomaly description :
2. Signs of Remanence:
3. Model (potent): Not completed
4. Strike & strike direction:
5. Dip & Dip Direction:
6. Depth to source:
7. Analytic Signal Image Check:
8. Any adjustment from currently planned hole required