



after the lead-in cable had been changed or serviced. These reversals were corrected and noted in quality control daily report.