

257270

19/11/90

07.46	Production	BB90-203	
10.45	Line change	To BB90-204	Recovering port inner gunstring
11.20			Approach to line 204 blocked by what looks like craypots. Cutting in to line with short run in to avoid the obstacles.
11.58	Production	BB90-204	
14.20	Downtime	Instrument	Line terminated for instrument memory fault, circling to resume line.
16.31	Production	BB90-204A	
17.41	Line change	To BB90-189	Recovering both starboard gunstrings.
19.49	Production	BB90-189	Starting line at point 12 kilometers from southern end to shoot into the shallows.
21.00	Line change	To BB90-189A	Circling to shoot second portion of line.
21.10			Results from measurement of the Charmouth/Hardwickes base line show an observed value of 31331.35 cf computed 31335.25 meters.
22.13	Production	BB90-189A	Completion of line shot on reciprocal heading.

20/11/90

00.00	Production	BB90-189A	
04.21	Line change	To BB90-187	Recovering the port inner gunstring.
06.15			Port inner gunstring redeployed.
06.40	Production	BB90-187	
11.42	Line change	To BB90-188	Recovering the port outer gunstring
14.23	Production	BB90-188	
20.00	Line change	To BB90-190	
22.33	Production	BB90-190	

21/11/90

00.00	Production	BB90-190	
01.22	Line change	To BB90-205	Recovering starboard outer gunstring
02.46	Production	BB90-205	Last line of survey
11.06	Mob/Demob	Source	Recovering all gunstrings
11.32	Mob/Demob	Streamer	Recovering streamer
13.20	Mob/Demob	Travel	Streamer on board, start transit back to Bell Bay for data drop.