

A minor problem was the occasional clogging of the shakers during drilling the sands between 1190 and 1300 metres.