

5.9 **Fishing Operations**

No fishing operations were performed on the well Flinders 1.

5.10 **Hole Problems**

No significant hole problems were encountered while drilling the well Flinders 1 other than a number of tight hole sections encountered while tripping. These sections generally caused no further problem after being reamed. In the 12¼" hole section Log Suite 1A was unable to pass 708m on the first attempt. A wiper trip was subsequently made in the hole with the 12¼" bit and the mud weight was raised to 9.99 ppg. The second run with Log Suite 1A was unable to pass 1240m.

5.11 **Perforating Record**

No perforating operations were performed on the Flinders 1 well.