



INTEGRATOR CHECK

100 psec/50'

6000 ft/50'

DOWN HOLE CALIBRATION AFTER SURVEY

Sonde Error

2.5-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

100,000

80,000

60,000

40,000

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

110,000

100,000

80,000

60,000

40,000

Mechanical Zero

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION AFTER SURVEY

140,000

100,000

80,000

60,000

40,000

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

140,000

100,000

80,000

60,000

40,000

Mechanical Zero

DOWN HOLE CALIBRATION AFTER SURVEY

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION AFTER SURVEY

140,000

100,000

80,000

60,000

40,000

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

140,000

100,000

80,000

60,000

40,000

Mechanical Zero

DOWN HOLE CALIBRATION AFTER SURVEY

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

Sonde Error

2.5-M

500 ft-M

100

1

Mechanical Zero

DOWN HOLE CALIBRATION AFTER SURVEY

140,000

100,000

80,000

60,000

40,000

Mechanical Zero

DOWN HOLE CALIBRATION BEFORE SURVEY

140,000

100,000

80,000

60,000

40,000

Mechanical Zero

FAST TRACK CALIBRATION		Test Loop Signal	
REF - R 100		Sonde Error	2.5-M
REF - VR 53		500 ft-M	
REF - R 100		100	
REF - VR 53		1	
REF - R 100		Mechanical Zero	

COMPANY		ESSO AUSTRALIA LTD	SCHL	FR 10395
WELL		NARIMBA 1	SCHL	TD 10400
FIELD		WILDCAT	DRLR	TD 10400
COUNTY		AUSTRALIA	State	TASMANIA
			KB	32
			DF	31
			GL	253