

Drilling Details

Rig Mindrill F30

Driller G. Steel

Commenced 10-2-1981

Completed 4-3-1981

Drilling conditions Generally good, water return was poor especially in the interval 124-126 which had to be cemented and redrilled. Drought conditions prevailed and caused major delays due to poor water return.

Core recovery approximately 97%