

---

Date 27 May, 1991

Ref

To D B Wallace

From A McNeill

At Burnie

At Burnie

Copies JWH

Keep

---

Subject

**MOUNT CHARTER REHABILITATION PLAN**

This memo is an initial attempt to highlight areas around Mount Charter that require rehabilitation. It is by no means exhaustive but could serve as a starting point for a rehabilitation plan. For detailed track/costean locations refer to plate MAC 89/CC.

**Mount Charter Dolerite**

Access to the MC-14 drill site should be maintained as new interpretations suggest the Que-Hellyer host horizon has not been tested in this area. However, the 3000E/4425N costeans are no longer required and could be rehabilitated. A dozer push from this costean to the 4200N/3200E trench was not inspected but could be rehabilitated if warranted. The 4300N/3200E and 3300E/4200N costeans should be left open as they provide probably the best exposure of the Mount Charter fault in this area. To the NE the 4800N/3800E costean was not visited but could be rehabilitated.

**South Charter**

Gordon's Hill Road, and the small trenches around 4000N/3600E, should be closed off and rehabilitated south of the MC-15 drill site. A north trending track from the MC-17 drill collar could be rehabilitated as should the drill site. This hole has been making water which is causing some erosion of the South Charter track. Further work on this drainage is required.

**Southwest Mount Charter**

Work required on the 3900N/4100E costean and the link track from the south Charter track to the MC-10 site has not been assessed, however regrowth on the track north of the 4000N/4100E costean is good with negligible erosion and no further work would appear to be necessary. The track from the MC-10 collar to the 4400N costean also shows good regrowth but some hand dug drainage may be required. The access track to the MC-19 drill site was not visited.