ENCLOSURE PS10

Schlumberger

EZSV PLUGS RUN #3 AND #4

CSU Field Log

OR_357D

COMPANY:	AMOCO AUSTRALIA PETROLEUM CO. 450692
WELL:	PELICAN #5
FIELD:	
STATE :	TASMANIA
RIG :	D.M.EPOCH
NATION:	AUSTRALIA
LOCATION:	SHOT POINT 240 LINE TNK4-87
SEC:	TWP: RGE:
LATITUDE:	40 20'43.259"S
LONGITUDE:	145 51'49.971"

OTHER SERVICES-
NONE

PERMANENT DATUM: MSL
ELEV. OF PERM. DATUM:
LOG MEASURED FROM: KB
21.4 M ABOVE PERM. DATUM
DRLG. MEASURED FROM: KB

ELEVATIONS-
KB: 21.4 M
DF: 21.1 M
GL: -78.3 M

PROGRAM
TAPE NO:
26.4
SERVICE
ORDER NO:
DME860312

DATE: 28 MAR 86
RUN NO: 4

DEPTH-DRILLER: 3412.0 M
DEPTH-LOGGER: 3412.0 M
BTM. LOG INTERVAL: 3133.0 M
TOP LOG INTERVAL: 2785.0 M

CASING-DRILLER:	2995 M	3647 M	4065 M
CASING-LOGGER:	2995 M	3647 M	4065 M
CASING:	9 5/8 IN.	7 IN.	5 IN.
WEIGHT:	53.50 LB/F	29.00 LB/F	21.000 LB/F
BIT SIZE:	12 1/4 IN.	8 1/2 IN.	6 IN.
DEPTH:	3002 M	3647 M	4267 M

LOGGING UNIT NO: 822
LOGGING UNIT LOC: VEA
RECORDED BY: G HIXON
WITNESSED BY: J.HARKINS

REMARKS:

DEPTH CORRELATED WITH CBL-WF-GR-CCL RUN #2 (12/02/86)

DISTANCE FROM CCL TO TOP SLIP ON PLUG: 2.7 MTRS
EZSV #3 SET AT 3111.0 MTRS: CASING SIZE 7 INCH
EZSV #4 SET AT 2923.3 MTRS: CASING SIZE 9 5/8 INCH

EQUIPMENT NUMBERS-

SHM-AA 1772 CAL-B BST-B

5 cm

ALL INTERPRETATIONS ARE OPINIONS BASED ON INFERENCES FROM ELECTRICAL OR OTHER MEASUREMENTS AND WE CANNOT, AND DO NOT GUARANTEE THE ACCURACY OR CORRECTNESS OF ANY INTERPRETATIONS, AND WE SHALL NOT, EXCEPT IN THE CASE OF GROSS OR WILLFUL NEGLIGENCE ON OUR PART, BE LIABLE OR RESPONSIBLE FOR ANY LOSS, COSTS, DAMAGES OR EXPENSES INCURRED OR SUSTAINED BY ANYONE RESULTING FROM ANY INTERPRETATION MADE BY ANY OF OUR OFFICERS, AGENTS OR EMPLOYEES. THESE INTERPRETATIONS ARE ALSO SUBJECT TO OUR GENERAL TERMS AND CONDITIONS AS SET OUT IN OUR CURRENT PRICE SCHEDULE.

CP 26.4 FILE 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
CCL	-13.00	7.0000
TENS(LB)	0.0	5000.0

EZSV # 2: Survey After Setting

CP 26.4 FILE 0



CP 26.4 ~~FILE~~ 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
CCL	-13.00	7.0000
TENS(LB)	0.0	5000.0

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	12.2500	IN	BHS	CASE	

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0
CCL	-13.00	7.0000

SCALE CHANGES

-13.00	CCL	7.0000
-15.00	2920	5.0000

EZSV # 2: Survey During Setting Pass.

CP 26.4 FILE 0



CP 26.4 FILE 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0
CCL	-15.00	5.0000

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	12.2500	IN	BHS	CASE	

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
CCL	-15.00	5.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0

EZSV # 2: Survey Before Setting

CP 26.4 FILE 0



CP 26.4 ~~FILE~~ 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
CCL	-15.00	5.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	12.2500	IN	BHS	CASE	

BS	12.2500	IN	BHS	CASE	

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
CCL	-15.00	5.0000
TENS(LB)	0.0	5000.0

EZSV # 1: Survey After Setting

CP 26.4 FILE 0



CP 26.4 ~~FILE~~ 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
CCL	-15.00	5.0000
TENS(LB)	0.0	5000.0

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	8.50000	IN	BHS	CASE	

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0
CCL	-15.00	5.0000

SCALE CHANGES

-15.00	CCL	5.0000
-17.00	3108	3.0000

EZSV # 1: Survey During Setting Pass.

CP 26.4 FILE 0



CP 26.4 FILE 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0
CCL	-17.00	3.0000

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	8.50000	IN	BHS	CASE	

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
CCL	-19.00	1.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0

EZSV # 1 : Survey Before Setting.

CP 26.4 FILE 0



CP 26.4 FILE 0

MRE	-17.00	3.0000
MLE	-17.00	3.0000
MDL	-17.00	3.0000
CCL	-19.00	1.0000
GS2	-10.00	10.000
GS1	-10.00	10.000
TENS(LB)	0.0	5000.0

SENSOR MEASURE POINT TO TOOL ZERO

CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	8.50000	IN	BHS	CASE	

Schlumberger

EZSV PLUGS RUN #3 AND #4

CSU Field Log

5 cm