ENCL 30

OR-0358A

Schlumberger

RFT SUITE 4

CSU Field Log

460152

COMPANY: AMOCO AUSTRALIA
WELL: CAPE SORELL NO. 1
FIELD: WILDCAT
STATE: TASMANIA
NATION: AUSTRALIA
LOCATION: SOUTHWEST TASMANIA
SEC: TWP: RGE:
LATITUDE: 042 08 09.54 S
LONGITUDE: 145 01 47.06 E

OTHER SERVICES-
DIL-SLS-GR
LDL-CNL-GR
CST

PERMANENT DATUM: M.S.L
ELEV. OF PERM. DATUM:
LOG MEASURED FROM: 72
72.0' ABOVE PERM. DATUM
DRLG. MEASURED FROM: KB

ELEVATIONS-
KB: 72.0'
DF: 71.0'
GL: -309.0'

PROGRAM
TAPE NO:
20.2
SERVICE
ORDER NO:
SEA 07 07

DATE: 4 SEP 1982
RUN NO: 1

DEPTH-DRILLER: 11578.0'
DEPTH-LOGGER: 11560.0'
BTM. LOG INTERVAL: 11556.0'
TOP LOG INTERVAL: 8998.0'

CASING-DRILLER:	1393'	4144'	9002'
CASING-LOGGER:	1393'	4140'	8998'
CASING:	20	13.37	9.6
WEIGHT:	133.0 LB/F	68.00 LB/F	47.00 LB/F
BIT SIZE:	17.5	12.25	8.5
DEPTH:	4161'	9033'	11578'

-

TYPE FLUID IN HOLE: FRESHWATER GEL
DENSITY: 9.6 LB/G
VISCOSITY: 49.0 S
PH: 10.0
FLUID LOSS: 6.0 C3
SOURCE OF SAMPLE: FLOWLINE
RM: 1.670 OHMM AT 60.0 DF
RMF: 1.290 OHMM AT 60.0 DF
RMC: 1.950 OHMM AT 60.0 DF
SOURCE RMF/RMC: PRESS /PRESS
RM AT BHT: 0.480 OHM AT 226. DF
RMF AT BHT: 0.370 OHM AT 226. DF
RMC AT BHT: 0.560 OHM AT 226. DF

TIME CIRC. STOPPED: 2000
TIME LOGGER ON BTM.: 2200

MAX. REC. TEMP: 226.0 DF

LOGGING UNIT NO: 33
LOGGING UNIT LOC: SEA
RECORDED BY: H GOH
WITNESSED BY: W BRYANT

REMARKS:

5 cm

EQUIPMENT NUMBERS-

RFT

ALL INTERPRETATIONS ARE OPINIONS BASED ON INFERENCES FROM ELECTRICAL OR OTHER MEASUREMENTS AND WE CANNOT, AND DO NOT GUARANTEE THE ACCURACY OR CORRECTNESS OF ANY INTERPRETATIONS, AND WE SHALL NOT, EXCEPT IN THE CASE OF GROSS OR WILLFUL NEGLIGENCE ON OUR PART, BE LIABLE OR RESPONSIBLE FOR ANY LOSS, COSTS, DAMAGES OR EXPENSES INCURRED OR SUSTAINED BY ANYONE RESULTING FROM ANY INTERPRETATION MADE BY ANY OF OUR OFFICERS, AGENTS OR EMPLOYEES. THESE INTERPRETATIONS ARE ALSO SUBJECT TO OUR GENERAL TERMS AND CONDITIONS AS SET OUT IN OUR CURRENT PRICE SCHEDULE.

FILE
101

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

2
FILE



2
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

3
FILE



3
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

4
FILE



4
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

6
FILE



6
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

7
FILE



7
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

8
FILE



8
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

9
FILE



9
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

11
FILE



11
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

12
FILE



12
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
DO	0.0		BHS	OPEN	
FLD	1.000	G/C3	HPT	68.57	DEGF
TZRV	453.0	OHM	TCRV	761.4	OHMS
HPSN	0000A-00		BS	8.500	IN

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

TENS .0 FEET GR -5.0 FEET

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

13
FILE



13
FILE

0.0 SGP (PSIG) 10000.		-10.00 PHUN(PSIG) 10.00	-10.00 PONE(PSIG) 10.00
		0.0 PTHO(PSIG) 20.00	0.0 PTEN(PSIG) 20.00

		PTHO(PSIG)	PTEN(PSIG)
		0.0 20.00	0.0 20.00
SGP (PSIG)		PHUN(PSIG)	PONE(PSIG)
0.0 10000.		-10.00 10.00	-10.00 10.00

FILE
1