12th JULY 1965

PANEL IRP-F 780
CART. IRC-F 707
SONDE IRS-M 355
TEST LOOP ITL-C 732

Test Loop Signal
500 mmho

Electrical Zero

UNBALANCE 1 mmho

Sonde Error 2½ mmho

Calibrate Signal
1030 mmho

Electrical Zero

Mechanical Zero

Calibrate Signal
THROUGH IAP-D

S.P RUN GOING DOWN
WITH POWER OFF