

5 cm

0374_2352

1.3.2 BOLD HEAD MINE SCHEDULES AND PRODUCTION 1975/76
 TABLE 1.3.2/1 PRODUCTION AND DEVELOPMENT SCHEDULE 1975/76

A R E A	1	2	3	4	5	6	7	8	9	10	11	12	13
<u>A LENS NORTH</u>													
CUT 1070 LEVEL	15												
CUT 1085 LEVEL	10	10											
<u>A LENS EAST</u>													
K46 RAISE					6								
K46 ORE PASS						8							
J47 ORE PASS						7							
I50 ACCESS RAISE							16						
I47 ORE PASSES								15					
<u>B LENS</u>													
DECLINE	20	20	10										
V53 STRIKE DRIVE	20	20	20	20									
			1000 0.4	1000 0.6									
T57 VENT RAISE					40								
S52 MANWAY RAISE						40							
V47 STRIKE DRIVE		20	20	20	20	20							
					500 0.6	500 0.6							
O57 VENT RAISE	10	10	15										
M47 VENT RAISE						45							