

UR 1953/40

TDH:3

1st April, 1953

MEMORANDUM:POSSIBILITIES OF UNDERGROUND WATER
ON PROPERTY OF MR. JOHN MURRAY,
SANFLY.

This property, is situated on the side of a dolerite hill between Sandfly and Kacots. The under-lying rock is not an aquifer and it is not recommended that any boring should be attempted.

Various means of obtaining additional water were discussed with Mr. Murray.

(Sgd.) Terence D. Hughes

GEOLOGIST

Director of Mines.