



Director of Mines, Hobart.

5th April, 1957

Left Burnie for Launceston at 7. 30 a.m. and arrived Launceston at 10. 30 a.m. Took EX casing and EX double tube core barrel to train and railed to Zeehan.

Visited Glasgow Engineering Coy. and arranged for 3 lengths of 3 inch pipe to be cut and  $1\frac{1}{8}$ " hole drilled in end of each piece. Also left a spare "A" rod coupling and short end of number two casing to be welded together to form a casing plug. These items need an order and are both for Zeehan drill when completed.

Left Launceston at 5 p.m. and arrived Hobart at 8 p.m.



(K.L. Evans)

SUPERINTENDENT OF DRILLING

The Director of Mines,  
HOBART.