



A mean of the fractional corrections so found were applied to the relevant patterns at the Slave Stations.

The final pattern settings and opposite slave readings were :-

At Slave I		At Slave II	
Patt. I	Patt. II	Patt. I	Patt. II
.48	.24	.24	.09

The calibration results showed that with the above settings applied, the residual corrections applicable will be :-

Area	Patt. I	Patt. II
Woodside	- .00	+ .00
Lakes Entrance	+ .02	+ .02
Cape Everard	- .01	- .03

This result is considered quite satisfactory and well within the specifications of the survey.

#### DIARY OF EVENTS

Friday,

25 August - Survey party travelled Sydney to Lakes Entrance.

Saturday, 26 - Calibration off Lakes Entrance. Severe gale forced boat to return to harbour before lane count could be carried out to buoys marking Marlin and Barracouta fields.

Sunday, 27 - Strong gale - bar at Lakes Entrance closed - computations of previous days calibration intersections.