



Raw readings and calibration computations are shown in Appendix 'B'.

The results obtained on 26 August in the area off Lakes Entrance were discarded as it was suspected that the very severe gale which followed and almost demolished Slave Station II at Woodside may have caused a change in Pattern II.

SUMMARY OF CALIBRATION RESULTS

Pattern I

(a)	Off Woodside - 29 August	
	Mean Fractional Correction	-.94
	Pattern I setting during calibration	.42
	Corrected Pattern Setting	<u>.48</u>
(b)	Off Lakes Entrance - 30 August	
	Mean Fractional Correction	+.08
	Pattern I setting during calibration	.42
	Corrected Pattern Setting	<u>.50</u>
(c)	Off Cape Everard - 31 August	
	Mean Fractional Correction	+.97
	Pattern I setting during calibration	.50
	Corrected Pattern Setting	<u>.47</u>
	<u>Accepted Pattern Setting</u>	<u>.48</u>