



-34-

- 15-11 After a call from Magnificent Creek, checked beacon 2, finding no problem.
- 16-11 Scouted Mt William, good coverage but very difficult to access, obtained permission from the ranger to use the local airstrip to load a helicopter and to occupy the site. Scouted Eddystone Point, some coverage of prospect, but not good.
- 17-11 Vessel on prospect, navigation performing normally.
- 18-11 Demobilised beacon 5 and remobilised on Mt William, using two sling loads by helicopter.
- 19-11 Vessel on prospect, navigation performing normally.
- 20-11 Vessel on prospect, navigation performing normally.
- 21-11 Beacon 3 (Hardwickes Hill) unstable, vessel using beacon 4, tested beacon 3 and power supply - all O.K. 1110-end of prospect, demobilised chain and returned to George Town.