



1. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 2. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 3. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 4. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 5. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 6. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 7. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 8. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 9. ALL DATA POINTS MUST BE PLotted ON THIS FORM.
 10. ALL DATA POINTS MUST BE PLotted ON THIS FORM.



ESSO PLOT - ZONE ALL POONBOON 1 Z11120
 XITOP= 6206.00 XIBOT=10685.00 HOLGATE=NO DATE=08/29/87
 SYMBOL=X CONDITIONS=(SW,LT,100)
 181 SYMBOL X POINTS AVAIL AVERAGE PHIE = 18.75 AVERAGE SW = 92.40
 JOB NAME=POONBOCC, PLOT TAPE VOL. SER.=TD8713



ESSO PLOT - ZONE ALL POONBOON 1 Z11120
 PICKETT PLOT - ZONE ALL
 XITOP= 6206.00 XIBOT=10685.00 HOLGATE=NO DATE=08/29/87
 SYMBOL=X CONDITIONS=(SW,LT,100)
 181 SYMBOL X POINTS AVAIL AVERAGE AT = 2.25 AVERAGE PHIE = 18.75
 JOB NAME=POONBOCC, PLOT TAPE VOL. SER.=TD8713

