

XX. AUXILIARY

- A. Two (2) Lincoln 400 amp welding machines.
- B. Two (2) air receivers, 100 cu. ft. capacity.
- C. One (1) Ingersoll-Rand air-drying automatic unit, refrigeration type.

Capacity : 100 SCFM
Working Pressure : 125 PSI
Electric Power : 440 Volts - 3 Phases
60 Cycles

- D. One (1) air compressor unit, diesel driven, with air receiver.

This unit delivers starting air for main diesel engines.