

CP 26.4 FILE 0


MRE	-17.00	3.0000				
MLE	-17.00	3.0000				
MDL	-17.00	3.0000		GS2	10.000	
CCL	-19.00	1.0000		GS1	10.000	TENS(LB)
						0.0 1000.0

SENSOR MEASURE POINT TO TOOL ZERO
CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	12.2500	IN	BHS	CASE	

MRE	-17.00	3.0000				
MLE	-17.00	3.0000				
MDL	-17.00	3.0000		GS2	10.000	
CCL	-19.00	1.0000		GS1	10.000	TENS(LB)
						0.0 1000.0



CP 26.4 FILE 0

MRE	-17.00	3.0000				
MLE	-17.00	3.0000				
MDL	-17.00	3.0000		GS2	10.000	
CCL	-19.00	1.0000		GS1	10.000	TENS(LB)
						0.0 1000.0

SENSOR MEASURE POINT TO TOOL ZERO
CCL 0.0 METER TENS 0.0 METER

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	12.2500	IN	BHS	CASE	