

Weathered (crumbly) igneous rock.

8116 - 8160 - as above

Gas Readings

7327 - 7710

cuttings - 3 - 200

Hot Wire 6 - 240

C₁ 400 - 24,000

C₂ 50 - 4000

C₃ 0 - 90

C₄ 0 - 80

peaks all in coal

7710' - 8040'

cuttings 7 - 200 ppm

Hot Wire 10 - 360

C₁ 600 - 30,000

C₂ 40 - 3,800

C₃ 0 - 200

C₄ 0 - 100

all peaks were at 8017' (in coal)

8040 - 8070

cuttings 5 - 40 ppm

Hot Wire 40 - 90

C₁ 4000 - 9000

C₂ 30 - 15,000

8070 - 8160

cuttings - 5 - 40

Hot Wire 10 - 20

C₁ 60 - 2000

C₂ 50 - 200

J. J.