

- 9550' - 60' 20% SS. aa - only a few aggregates with show
70% Sls aa
10% Coal
- 9560 - 70' 30% SS. aa
70% Sls. aa
TR Coal
- 9570' - 80' 100% Coal (no nit gas back)
TR Sls
- 9580 - 90' 90% Sls
10% Coal
TR SS
- 9590' - 9600' 10% Sls
90% Coal
- 9600 - 10' 70% Sls.
30% Coal
TR SS
- 9610 - 20' 50% SS white, f-med. very weak
50% Sls. lit blue pin pt flux - no nit
TR Coal. (51 unit gas back associated)
- 9620' - 30' 20% SS aa
70% Sls aa
10% Coal
- 9630' - 40' 40% SS aa - no show. mineral flux on
60% Sls
TR Coal
- 9640' - 50' 20% SS aa (much fine material
50% Sls being lost through
TR Coal shaker).