

100% Coal bleeding gas.
Cuts easily et blue

80% Coal
10% SS aa
10% site + shale

50% ss ae
50% silt & cb shale
Tr coal

40% salt & sh. shale
60% coal &

20% SS, aa
80% Coal + cl silt + shale

40% ss. aa ...
50% sst + chalc
10% coal

10⁰⁰ SS on
20⁰⁰ db Sls & shale
20⁰⁰ coal

102 ss, aa, with a ^{dull} green blue
fluv a v. slight lt blue
cut

90% coal. bleeding tremendous
amount of gas.

100% Coal. bleeding gas

50% Sil. & shale
70% Coal.

