




CP 28.2A

FILE 0

DEVI<DEG>		TENS<LB>	
-1.000	9.0000	10000.	0.0
RB<DEG>		C2<IN>	
-40.00	360.00	26.000	6.0000
AZIM<DEG>		C1<IN>	
-40.00	360.00	26.000	6.0000

SENSOR MEASURE POINT TO TOOL ZERO

C1 0.0 METER
PP 0.0 METER
RC 0.0 METER
FEP2 0.0 METER
DEVI 0.0 METER
AZIM 0.0 METER
RC1 0.0 METER
SHDT 0.0 METER
FC3 0.0 METER
FC1 0.0 METER
FC0 0.0 METER

C2 0.0 METER
TEMP 0.0 METER
EMEX 0.0 METER
REFE 0.0 METER
FEP1 0.0 METER
RB 0.0 METER
RC2 0.0 METER
TENS 0.0 METER
FC4 0.0 METER
FC2 0.0 METER

5 cm

PARAMETERS

NAME VALUE UNIT
MCT 72
BHS OPEN
BS 12.2500 IN

NAME VALUE UNIT
MDEC 0 DEG
STYP HDSF