

CP 28.4 FILE 15 05-MAR-86 04:26


0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

PARAMETERS					
NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	DPEN	
FLD	1.00000	G/C3	HPT	306.151	DEGF
TZRV	453.000	DMHS	TCRV	761.450	DMHS
HPSN	0000A-00011		RPU	PSIG	
RFTT	334.500	DEGF	FDEP	3893.09	M
SGSN	53153		CDAT	31 12 85	

SENSOR MEASURE POINT TO TOOL ZERO  
TENS 7.90 METER GR 6.38 METER

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

CP 28.4 FILE 16 05-MAR-86 04:30



CP 28.4 FILE 16 05-MAR-86 04:39


0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

PARAMETERS					
NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	DPEN	
FLD	1.00000	G/C3	HPT	306.151	DEGF
TZRV	453.000	DMHS	TCRV	761.450	DMHS
HPSN	0000A-00011		RPU	PSIG	
RFTT	334.500	DEGF	FDEP	3890.50	M
SGSN	53153		CDAT	31 12 85	

SENSOR MEASURE POINT TO TOOL ZERO  
TENS 7.90 METER GR 6.38 METER

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

CP 28.4 FILE 17 05-MAR-86 04:49



CP 28.4 FILE 17 05-MAR-86 04:51


0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

PARAMETERS					
NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	DPEN	
FLD	1.00000	G/C3	HPT	306.151	DEGF
TZRV	453.000	DMHS	TCRV	761.450	DMHS
HPSN	0000A-00011		RPU	PSIG	
RFTT	334.500	DEGF	FDEP	3889.98	M
SGSN	53153		CDAT	31 12 85	

SENSOR MEASURE POINT TO TOOL ZERO  
TENS 7.90 METER GR 6.38 METER

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

CP 28.4 FILE 18 05-MAR-86 04:53



CP 28.4 FILE 18 05-MAR-86 04:56


0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

PARAMETERS					
NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	DPEN	
FLD	1.00000	G/C3	HPT	306.151	DEGF
TZRV	453.000	DMHS	TCRV	761.450	DMHS
HPSN	0000A-00011		RPU	PSIG	
RFTT	334.500	DEGF	FDEP	3889.49	M
SGSN	53153		CDAT	31 12 85	

SENSOR MEASURE POINT TO TOOL ZERO  
TENS 7.90 METER GR 6.38 METER

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

CP 28.4 FILE 19 05-MAR-86 04:58



CP 28.4 FILE 19 05-MAR-86 05:02


0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

PARAMETERS					
NAME	VALUE	UNIT	NAME	VALUE	UNIT
BS	6.00000	IN	BHS	DPEN	
FLD	1.00000	G/C3	HPT	306.151	DEGF
TZRV	453.000	DMHS	TCRV	761.450	DMHS
HPSN	0000A-00011		RPU	PSIG	
RFTT	327.000	DEGF	FDEP	3674.94	M
SGSN	53153		CDAT	31 12 85	

SENSOR MEASURE POINT TO TOOL ZERO  
TENS 7.90 METER GR 6.38 METER

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	

CP 28.4 FILE 20 05-MAR-86 05:13



CP 28.4 FILE 20 05-MAR-86 05:19

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	



CP 28.4 FILE 20 05-MAR-86 05:19

0.0	20000.	-10.00	10.000	-10.00	10.000
SGP (PSIG)		PHUN		PDNE	
-320.0	80.000	0.0	20.000	0.0	20.000
HSPC(RPS)		PTH0		PTYN	