



FILE
101

DEVI(DEG)		CR (IN)	
-1.000	9.0000	30.000	10.000
RB (DEG)		C1 (IN)	
-40.00	360.00	30.000	10.000
AZIM(DEG)			
-40.00	360.00		

SENSOR MEASURE POINT TO TENSION REFERENCE POINT

RB	.0	FEET	AZIM	.0	FEET
FEP1	.0	FEET	DEVI	.0	FEET
REFE	.0	FEET	FEP2	.0	FEET
EMEX	.0	FEET	RC	.0	FEET
C2	.0	FEET	C1	.0	FEET
RC2	.0	FEET	RC1	.0	FEET
TEMP	.0	FEET	PP	.0	FEET
FC0	.0	FEET	TENS	.0	FEET
FC2	.0	FEET	FC1	.0	FEET
FC4	.0	FEET	FC3	.0	FEET
SHDT	.0	FEET			

PARAMETERS

NAME	VALUE	UNIT	NAME	VALUE	UNIT
PVUM	1.00000		BS	12.2500	IN
STYP	HDSF		HCT	72	DEG
BD	0.0	F	BHS	OPEN	

