

SITE_ID	FROM_DEPTH	TO_DEPTH	EXP_STATUS	METHOD	EQUIP	DATE	SHIFT	COMPANY	RIG	COMMENTS
KWRC001	0	10	N	RC6 TRI		9/24/2008	D	EDRILL		PRD Multistar 2000
KWRC001	0	10	N	CAS		9/24/2008	D	EDRILL		PVC + Gypsum
KWRC001	11	28	N	RC6 HMF		9/24/2008	D	EDRILL		
KWRC001	29	46	N	RC6 HMF		9/25/2008	D	EDRILL		
KWRC002	0	16	N	RC6 HMF		9/25/2008	D	EDRILL		PRD Multistar 2000
KWRC002	0	16	N	CAS		9/25/2008	D	EDRILL		PVC + Gypsum
KWRC002	17	40	N	RC6 HMF		9/25/2008	D	EDRILL		
KWRC002	41	60	N	RC6 HMF		9/26/2008	D	EDRILL		
KWRC003	0	10	N	RC6 HMF		9/26/2008	D	EDRILL		PRD Multistar 2000
KWRC003	0	10	N	CAS		9/26/2008	D	EDRILL		PVC + Gypsum
KWRC003	11	60	N	RC6 HMF		9/26/2008	D	EDRILL		
KWRC004	0	10	N	RC6 HMF		9/28/2008	D	EDRILL		PRD Multistar 2000
KWRC004	0	10	N	CAS		9/28/2008	D	EDRILL		PVC + Gypsum
KWRC004	11	60	N	RC6 HMF		9/28/2008	D	EDRILL		
KWRC005	0	10	N	RC6 HMF		9/28/2008	D	EDRILL		PRD Multistar 2000
KWRC005	0	10	N	CAS		9/28/2008	D	EDRILL		Gypsum + PVC
KWRC005	11	46	N	RC6 HMF		9/29/2008	D	EDRILL		

EOF