

131

Sample No.	Major	Minor	Heavy Trace 1,000 - 10,000 ppm (0.1-1%)	Trace 100 - 1,000 ppm (0.01-0.1%)	Faint Trace 10 - 100 ppm (0.001-0.01%)	Very Faint Trace 1 - 10 ppm (0.0001-0.001%)
03/0701 M-03	Si, Fe, Al, Ca	Mg, Na, K	Zn, Ti	<u>W</u> , <u>Sn</u> , <u>Mo</u> , Mn	<u>Bi</u> , Cu, Li, Zr, Pb, Cr, Co, V, B, As, Ni, Cd, Sr, Be, Ga	Ge, Ag, Y
03/0701 M-05	Si, Al, Ca	Fe, Mg, Mn	Ti	Zn, Cr, K	Pb, Na, P, Zr, V, Li, Ni, Bi, Sn, Y	Co, Be, B, Mo, Cu, Ga, Ag

Elements not sought: Hg, Re,

Other elements not detected at limits quoted in attached sheet: Ta, Nb, Mn, Pt, Pd, Os, Ir, Rh, Ru, Au, Ag, Hg, Pb, Bi, Sb, Ba, La, Ce, Nd, Pr, Er, Sm, Eu, Gd, Dy, Ho, Er, Yb, Lu, Sc, W,

Com. 6. Ord 2x.