

APPENDIX 8      HYDROGEOLOGYA.8.1      Introduction

Thirteen piezometers were installed at seven sites in the Selbourne, Loatta, and Pipers Lagoons sub-basins. The location of these sites is shown in Figure 7. Depths at which piezometers are set, and zones that the piezometers monitor are summarized in Table 13 and Figure 8. Installation of piezometers is detailed in Section A.8.3.

A.8.2      Piezometer Nomenclature

Exploratory drill holes with the suffix P, for example C064 (P) are drill holes in which piezometers are installed. The suffixes P1 and P2 refer to piezometer one, and piezometer two respectively, and only apply when two piezometers are installed in the one drill hole.