

PD83 PT-07

<u>From (m)</u>	<u>To (m)</u>	
0	2	Dolerite, moderately weathered, scree/talus deposit
2	4	Clay, pale brown
4	8	Clay, medium brown, (? extremely weathered dolerite), with slightly weathered dolerite fragments
8	18	Dolerite, fresh, medium grained

EOH

Comments

- (i) No sample recovery from 10-18, due to broken PVC casing but penetration rate and dolerite chips around collar indicated solid dolerite.
- (ii) Poor sample return combined with operational problems with the down hole hammer bit, necessitated the abandonment of the hole at 18m.