


**BRIGHTON
BLOCK**

98-4170

232001

(Grieves Rd
Turnrock)



23rd April 1998

Attention: Teresa

Mineral Resources Tasmania
Gordons Hill Road
Rosny Park 7018

To Whom It May Concern

I Ken Midson applied and received EL 48/96 to establish a course sand supply pit for the building industry in Southern Tasmania.

The initial tests of surface sand indicated that it may be suitable for concrete block production. I then drilled the area to determine depth and found the sand was still present at 2m and over an area of approx 10 hectares. Deciding that there was adequate quality I engaged a D9 size Bulldozer to see if the sand could be won at a competitive price as the sand in situ was very hard.

The Bulldozer cut a trench approx 35m long x 3m wide and 4m deep. The winning of the product with a bulldozer was reasonably successful.

Unfortunately as the sand got deeper the silt content rose sharply which made the product unsuitable for concrete products because the water volume had to be increased thereby causing the cement content to be increased thus making the sand uneconomical.

Therefore I filled back in the trench and reinstated the site. I hereby make application for my \$2,000 rehabilitation bond to be refunded.

MICROFILMED
FICHE No.014600-

Yours Sincerely

Ken Midson

98-4170

FINAL REPORT - EL 48/96
K A MIDSON

MINERAL RESOURCES
TASMANIA
EL 48/96
19 APR 1998
See folio 30

232002

LAND TENURE:

PRIVATE PROPERTY

SF-MUFL

Part of Spinning
Gum F.R. (EX)

NT

EL 48/96

REFER TO THIS MAP AS: LTIS SHEET 8312 EDITION 1985

