

106

82/10

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 106 Grid Reference 088 613 Map Sheet No 82
Name of Owner/Quarry: G. Johnson - Buddins Hill - Malbina

Working Pit/Disused Pit/New Locality: 8yt

Past Production: 1540 m³ Estimated Reserves: Small

Description of site: Surface scraping (gutter type) on moderate slope - northern aspect, light bush - scrub.

Limits to expansion: None - apart for visual effects

Thickness of overburden: 10-15 cm poor soil

Sources of information: RAAM Field: 6/12/78 Laboratory: Ref. No.:

Sizing analysis: Date:

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. P.I. L.S. D.R.

Special tests:

Group Symbol (unified soil classification system): SM - GM

Geological Description: Angular silty gravel.
Moderate to high fines content.
Pebbles mainly small.

History:

Remarks: 35 x 55 x 8.