338087 OR-334 Enclosure 8

SCHLUMBERGER FORMATION TESTER

COUNTY AUSTRALIA
Field or LOCATION WILDCAT
WELL CORMORANT 1
COMPANY ESSO

COMPANY ESSO
WELL CORMORANT 1
FIELD WILDCAT
COUNTY AUSTRALIA STATE TASMANIA
LOCATION 145° 31' 35".7 E 39° 34' 22".8 S
Sec. Twp. Rge.
Other Services: IES, FDC GR

Permanent Datum: MSL, Elev. 0
Log Measured From KB, 100 Ft. Above Perm. Datum
Drilling Measured From KB
Elev.: K.B. 100 D.F. 99 G.L.

Date	23 July 1970
Run No.	1
Test No's.	1-6
Type of Test	Open Hole ☒ Cased Hole ☐ Open Hole ☐ Cased Hole ☐
Type Fluid in Hole	Q Broxin. XP 20
Dens. / Visc.	10.4 / 40
pH / Fluid Loss	10 / 8.2
Source of Sample	circulation
Rm @ Meas. Temp.	1.73 @ 74 °F
Rmf @ Meas. Temp.	1.84 @ 59 °F
Rmc @ Meas. Temp.	0.7 @ 198 °F (chart)
Source: Rmf / Rmc	press
Rm @ BHT	0.64 @ 198 °F
Time Since Circ.	
Max. Rec. Temp.	198 °F
Recorded By	GASTALDY
Witnessed By	HICKS

BORE-HOLE RECORD

RUN No.	Bit	From	To
1	12¼"	3002	8663

CASING RECORD

Size	Wgt.	From	To
13⅜"		0	2952

FIELD PRINT

FOLD HERE

The well name, location and borehole reference data were furnished by the customer.

Run No.	1
Operating rig time	24 hrs.
Logging Truck No.	2072
F.T. Truck No.	-
F.T. Engineer	GASTALDY
F.T. Operator	WRIGHT
Location	SAL

REMARKS: Test # 3. On completion of the test could not close the sample. Part of it was lost
Test # 4. Erratic readings of sample gauge during pressure build up.
Test # 5. Mud run. Lost seal when shooting shaped charge
Test # 6. Lost the seal when we opened the segregator. Reverse fire technique used.

RECORDED TESTER POSITION

Test No. 1





RECORDED TESTER POSITION

Test No. 2





RECORDED TESTER POSITION

Test No. 3





RECORDED TESTER POSITION

Test No. 4





RECORDED TESTER POSITION

Test No. 5