

SAMPLE	COPPER %
A	TR.
B	0·3
C	0·1
D	No Sign Of Mineralization No Sample Taken.
E	TR
F	0·1
G	0·8
H	0·7
I	0·3
J	N.S.O.M. No Sample Taken.
K	0·1
L	N.S.O.M. No Sample Taken
M	N.S.O.M No Sample Taken
N	0·1
O	TR
P	N.S.O.M. No Sample Taken.
Q	TR
R	0·1
S	1·8
T	0·1
U	0·1
V	0·3
W	TR
X	TR
Y	N.S.O.M. No Sample Taken.
Z	TR
Al.	TR
Bl.	0·3

Pyritized Schist

Quartzitic Chloritic Schist and Chloritic Schist in Sheared Quartz-Felspar (Porphyry Dyke)

Schist Planes

N.B. A Pyritized Area of Chloritic Schist also occurs about 1 Mile to the North of Lake Rolleston Secs 2230/93M & 4422/93M

03-4912

LAKE DORA.

COPPER WORKINGS.

SCALE :- 5 CHAINS - 1 INCH.

5 cm

6

Circa May 1938

ET 91