



REVISIONS	DESCRIPTION	INITIALS	APPROVAL	COPY
1	22/6/78 S9 DRIVE BEYOND SWAN FAULT ALTERED TO CLEAR FAULT	WJ	PLANNING ENG.: WJ 22/6/78 SENIOR PLAN. ENG.: ABSENT MINE SUPT.: G.E. 23/6/78 G. MINING SUPT.: G.E. 23/6/78 SENIOR SURV'R.: G.E. 23/6/78 SENIOR GEOLOGIST: G.E. 23/6/78 SURVEYOR: G.E. 23/6/78	2

SCALE 1:500	LOCATION DOLPHIN MINE	SUBJECT -240m RL DIAMOND DRILLING	north		GRASSY 28 JUNE 1978 KING ISLAND
					PLAN NUMBER 03 DM 16 1001