



<p>APPROVAL</p> <p>PLANNING ENG.: <i>[Signature]</i> COPY</p> <p>SENIOR PLAN. ENG.: <i>[Signature]</i> 16-2-80</p> <p>MINE SUPT.: <i>[Signature]</i> 23/2/80</p> <p>G. MINING SUPT.: <i>[Signature]</i> 28/2/80 2</p> <p>SENIOR SURV'R.: <i>[Signature]</i></p> <p>SENIOR GEOLOGIST: <i>[Signature]</i> 25/4/80 1</p> <p>SURVEYOR:</p>		<p>SCALE 1:500</p>	<p>LOCATION</p> <p>BOLD HEAD MINE. 10650 - 10600 N</p> <p>SUBJECT</p> <p>"D" LENS ORE BODY</p> <p>Access FROM K57</p> <p>DRAWING 1A.</p> <p>north</p>	<p>KIS KING ISLAND SCHEELITE</p> <p>A DIVISION OF WARMAN INTERNATIONAL</p> <p>GRASSY KING ISLAND</p> <p>PLAN NUMBER</p> <p>03 BH 04 - 1013</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	--------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------