



T
S
R
Q
P
O
N
M
L
K

64 | 63 | 62 | 61 | 60 | 59 | 58 | 57 | 56 | 55 | 54 | 53 | 52 | 51 | 50

| APPROVAL | | COPY |
|--------------------|--------------------|------|
| PLANNING ENG.: | <i>[Signature]</i> | |
| SENIOR PLAN. ENG.: | <i>[Signature]</i> | |
| MINE SUPT.: | <i>[Signature]</i> | 2 |
| G. MINING SUPT.: | <i>[Signature]</i> | |
| SENIOR SURV'R.: | <i>[Signature]</i> | |
| SENIOR GEOLOGIST: | <i>[Signature]</i> | 1 |
| SURVEYOR: | <i>[Signature]</i> | |

SCALE 1:500
 C'2' - 10500N to 10575N STOPE ACCESS

LOCATION
 BOLD HEAD MINE
 SUBJECT

KIS KING ISLAND SCHEELITE
 A DIVISION OF WARMAN INTERNATIONAL

GRASSY 27 FEBRUARY 1979 KING ISLAND
 PLAN NUMBER 03804-1006

north