

A horizontal line segment with vertical tick marks at both ends. Above the segment, the text "5 cm" is written.

03 BH 02 2007

DEVELOPMENT SCHEDULE 1978 - 79

BOLD HEAD MINE

		YELLOW	PURPLE	LIGHT BLUE	ORANGE	DARK GREEN	BLACK	LIGHT GREEN	YELLOW-ORANGE	BROWN	BLUE	GREEN	LIGHT GREY	RED	TOTAL	
		1	2	3	4	5	6	7	8	9	10	11	12	13		
BUDGET	MAIN DECLINE	MD	20	20	20	30	30	35		35	30	20	10	30	30	310
	WASTE DEVELOPMENT	WD	45	35	35	25	27	15		10	35	35	36	25	25	348
	STOPE DEVELOPMENT	SD	30	45	50	50	50	55	60	60	60	50	40	50	50	650
	RAISE BORE	RB				40	30	40						30		140
	HAND RISING	HR	15	15	15	15	15	15	15	15	15	15	15	15	15	195
			110	115	120	160	152	160	75	120	140	120	101	150	120	1643
	TOTAL															
MAIN DECLINE	MD	20	20	20	25	25	30		35	30	20	25	30	30	310	
WASTE DEVELOPMENT	WD	28	35	35	30	30	20		20	25	40	35	25	25	348	
STOPE DEVELOPMENT	SD	45	50	50	50	50	55	60	50	50	45	45	50	50	650	
RAISE BORE	RB				40	30	40							30	140	
HAND RISING	HR	15	15	15	15	15	15	15	15	15	15	15	15	15	195	
TOTAL		108	120	120	160	150	160	75	120	120	120	120	150	120	1643	
TOTAL [DRIVING]		93	105	105	105	105	105	60	105	105	105	105	105	105	1308	
MAIN DECLINE	MD	20	20	20	20	10	15		15	10	10	10	15	10	175	
MAIN QUARTZITE DRIVE	MD				5	15	15		20	20	10	15	15	20	135	
R 52 C.W. X.CUT	WD	15	15	15	15	10									70	
D LENS - UPPER P64	WD		5	5											10	
D LENS - LOWER	WD					5	5								10	
C2 ACCESS - 895 R.L.	WD											10		5	15	
MANWAY X.CUT - 908 R.L.	WD												10		10	
C2 W ACCESS - 650 N - K 65	WD									5	15				10	
L 43 ACCESS TO ORE PASS	WD	10													10	
R 60 C2 TWIN	WD		10												10	
A LENS	WD						10		10	10	10	10	10	10	70	
B LENS	WD			10	10	10				5	5	5	5	10	60	
C2 E. ACCESS - 550 N	WD										10	10			20	
H59 F.W. DRIVE	SD		15	15	15	15	15	15	15	10					115	
R60 - C2 TWIN	SD	5	5	10	10	10	20	20							80	
D LENS - UPPER	SD			5	5	10									20	
C2 ACCESS - 650N	SD											20	20		40	
C2 ACCESS - 550 N	SD									10	5				15	
C1 STOPE X.CUTS	SD	15	15	15	15	15	15	10	10	10	10	5			135	
C1 STOPE RAMPS	SD							15	15	10	15	5			60	
B MAIN STOPE RAMPS	SD	15	15	5	5		5		5	10	10	10	10	10	100	
HAND RISING		15	15	15	15	15	15	15	15	15	15	15	15	15	195	
RAISE BORE					40	30	40							30	140	
WASTE DEVELOPMENT		3	5	5	5	5	5		10	5					43	
STOPE DEVELOPMENT		10							5		5	5	20	40	85	
1977 - 78 OVERRUN																
UNSCHEDULED DEVELOPMENT																