



Survey station, Line pgs. FLP, BLP	+	Conglomerate contact	○ ○	Shear	—
Rise - down	⊙	Fault zone	—	Lampophyre Dyke	—
Rise - through	⊗	Cable hole	—		
Rise - up	⊕	Diamond drill hole collar	—		
Sets	□	Diamond drill hole intersection	—		
Ore outline	—	Diamond drill hole, end of hole	—		

JAN.-DEC. 1993

THE MOUNT LYELL M. & R. CO. LTD.		DRAWN	APPROVED
DATE: OCT. 1991	SCALE: 1:500	CHECKED	APPROVED
PRINCE LYELL MINE		CHECKED	APPROVED
270 SUB-LEVEL 60 SERIES		DRAWING NUMBER	
		A0-602	
		SHEET NUMBER —	

UPDATED 11/16/93



0381-036