


- | | | | | | |
|------------------------------------|---------|---------------------------------|-----|------------------|---|
| Survey station, Line pegs FLP, BLP | + | Conglomerate contact | ○ ○ | Shear | — |
| Rise - down | ⊙ | Fault zone | — | Lamprophyre Dyke | — |
| Rise - through | ⊗ | Cable hole | — | | |
| Rise - up | ⊗ | Diamond drill hole collar | ○ | | |
| Sets | □ □ □ □ | Diamond drill hole intersection | — | | |
| One outline | — | Diamond drill hole, end of hole | — | | |

JAN. - DEC. 1992



THE MOUNT LYELL M. & R. CO. LTD.		DRAWN	APPROVED
DATE: OCT. 1991	SCALE: 1:500	CHECKED	APPROVED
PRINCE LYELL MINE		DRAWING NUMBER	
270 SUB-LEVEL 60 SERIES		AO-602	
		SHEET NUMBER	

0.92 - 04.0