



- | | | | | | |
|------------------------------------|---|---------------------------------|---|------------------|---|
| Survey station, Line pegs FLP, BLP | + | Conglomerate contact | ○ | Shear | — |
| Rise - down | ● | Fault zone | — | Lamprophyre Dyke | — |
| Rise - through | ⊗ | Cable hole | ○ | Collapsed ground | — |
| Rise - up | ⊙ | Diamond drill hole collar | ⊠ | | |
| Sets | □ | Diamond drill hole intersection | ⊕ | | |
| One outline | — | Diamond drill hole, end of hole | — | | |

JAN. - DEC. 1992

UPDATED DEC 92
 5 cm

THE MOUNT LYELL M. & R. CO. LTD.		DRAWN	APPROVED
DATE: JULY, 1992	SCALE: 1:500	CHECKED	APPROVED
PRINCE LYELL MINE		DRAWING NUMBER	
300 SUB-LEVEL 60 SERIES		A0-603	
SHEET NUMBER		—	

033-041