



SECTION III

OPERATIONS

No major problems were encountered on this prospect. The weather was fair (force 2-4) with large swells, resulting in occasional noisy traces from front end and tailbuoy jerk.

The crew took advantage of time which would have otherwise been lost because of sea conditions to call into Portland to resupply.

Respectfully submitted,
GEOPHYSICAL SERVICE INTERNATIONAL

Charlie G. Martin
Marine Operations mgr.

Quality Control Seismologist