

257235

ACTIVITY REPORT FOR THE 17TH OF NOVEMBER

TIME	ACTIVITY	TYPE	HOURS	CHARGE
.00	Downtime	Weather	9.08	9.08
9.05	Downtime	Source	1.80	0.00
10.53	Production	BB90-194	3.12	0.00
14.00	Line change	To BB90-198A	2.48	0.00
16.29	Production	BB90-198A	0.78	0.00
17.16	Line change	To BB90-198A	1.22	0.00
18.29	Production	BB90-195A	2.93	0.00
21.25	Line change	To BB90-192	1.52	0.00
22.56	Production	BB90-192	1.07	0.00
		Total:	24.00	9.08

ACTIVITY SUMMARY

ACTIVITY	HOURS	CHARGE
Downtime	10.88	9.08
Line change	5.22	0.00
Production	7.90	0.00
Total:	24.00	9.08