

257259

ACTIVITY: PRODUCTION START: 16.29 END: 17.16 DATE: 90/11/17
 LINE- BB90-198A STATUS: COMPLETE LINE DIRECTION: 233°

FSP: 1361 File: 1361 Tape No: 11058 Water Depth: 49 m. FCSP: 1421
 LSP: 1658 File: 1658 Tape No: 11060 Water Depth: 47 m. LCSP: 1658
 Total Coverage: 7.450 kms Chargeable Coverage: 5.950 kms
 Total bad traces: 0 Total gun failures: 0 Total misfires: 0

STREAMER

SOL Noise Av: 7.9 μ bars Depth: 10.7 m. \pm 0.2 Feather: 0.9 ° to stbd
 EOL Noise Av: 6.4 μ bars Depth: 10.6 m. \pm 0.3 Feather: 0.8 ° to stbd
 Comment: At SOL and EOL data and noise records affected by ship noise
 from two different vessels.

ENERGY SOURCE

SOL Volume: 2180 ci @ Pressure: 1810 psi EOL Volume: 2180 ci
 Comment:

NAVIGATION

Stations in use: Hardwickes, East Sandy, Stony Point
 SOL Ranges: 25660.7 m. : 21260.1 m. : 37145.8 m.
 SOL Antenna Position: 040 46 17.48 S: 147 21 15.84 E CEP: <1 meters
 EOL Antenna Position: 040 48 41.76 S: 147 17 01.77 E CEP: <1 meters
 Comment:

Navigation quality: Good Overall Data Quality: Good

Misfire report:

Wind Direction/Force: WNW/4 Sea State: 3

GENERAL COMMENTS: Line complete with overlap.

ACTIVITY: PRODUCTION START: 00.51 END: 03.48 DATE: 90/11/15
 LINE- BB90-199A STATUS: COMPLETE LINE DIRECTION: 233°

FSP: 101 File: 101 Tape No: 10974 Water Depth: 35 m. FCSP: 101
 LSP: 1273 File: 1270 Tape No: 10985 Water Depth: 44 m. LCSP: 1273
 Total Coverage: 29.325 kms Chargeable Coverage: 29.325 kms
 Total bad traces: 0 Total gun failures: 2 Total misfires: 3

STREAMER

SOL Noise Av: 2.0 μ bars Depth: 10.3 m. \pm 0.3 Feather: 7.6 ° to port
 EOL Noise Av: 2.4 μ bars Depth: 10.3 m. \pm 0.3 Feather: 0.3 ° to stbd
 Comment: Trace 155 spiking occasionally.

ENERGY SOURCE

SOL Volume: 2180 ci @ Pressure: 1850 psi EOL Volume: 2100 ci
 Comment: SP 267 gun 54 off, timing. SP 372 gun 8 off, timing.

NAVIGATION

Stations in use: Charmouth, East Sandy, Stony Point
 SOL Ranges: 29534.1 m. : 65276.7 m. : 86850.2 m.
 SOL Antenna Position: 040 30 43.35 S: 147 50 03.36 E CEP: 2-3 meters
 EOL Antenna Position: 040 40 09.86 S: 147 33 27.92 E CEP: <1 meters
 Comment: SP 768-783 dropped Charmouth. SP 1147 Charmouth replaced
 by Hardwickes. SP 1186 Hardwickes replaced by Charmouth again

Navigation quality: Poor Overall Data Quality: Good

Misfire report: SPs 764,766,1142 missed because of navigation quality

Wind Direction/Force: W/2 Sea State: 3

GENERAL COMMENTS: Offline by up to 48 meters SPS 1168-1226, currents?