

PAGE 6

*	PLOTBUCK(	0)=YES	OPTION (	1)=	1.0000	*	
*	PLOTREF (	0)=M	PLOTPICK(	0)=YES		*	
*	RESPLOT (	0)=NO	PLTSCALE(	0)=	500.0000	*	
*	RHOF (	2)=	1.0000	RHOF (	1)=	1.0000	*
*	RHOGLM (	2)=	2.7100	RHOGLM (	1)=	2.7100	*
*	RHOGSD (	2)=	2.6500	RHOGSD (	1)=	2.6500	*
*	RMDAT (	0)=	73164.0000	RM (	0)=	0.6700	*
*	RMF (	1)=	0.5800	RMF (	0)=	0.5800	*
*	RMF (	3)=		RMF (	2)=		*
*	RMF (	5)=		RMF (	4)=		*
*	RMFTMP (	1)=	70.0000	RMF (	6)=		*
*	RMFTMP (	3)=		RMFTMP (	2)=		*
*	RMFTMP (	5)=		RMFTMP (	4)=		*
*	RMFTMP (	0)=	70.0000	RMFTMP (	6)=		*
*	RWPLOT (	0)=NO	RMTEMP (	0)=	100.0000	*	
*	STDOFFA (	1)=	0.0	STDOFF (	1)=	1.5000	*
*	SW (	0)=	3.0000	SURFTMP(	0)=	70.0000	*
*	SWCUT2 (	0)=	80.0000	SWCUT1 (	0)=	50.0000	*
*	SWMETH2 (	0)=NO	SWMETH1 (	0)=YES		*	
*	TAPE (	0)=	104.0000	SWMETH3 (	0)=NO	*	
*	TF (	0)=	10431.0000	TEMPREF (	0)=F	*	
*	TOPRUN (	2)=		TOPRUN (	1)=	2808.0000	*
*	TOPRUN (	4)=		TOPRUN (	3)=		*
*	TOPRUN (	6)=		TOPRUN (	5)=		*
*	USEZEROS(	0)=NO	TRACE (	0)=NO		*	
*	VSHGRMAX(	2)=	90.0000	VSHGRMAX(	1)=	60.0000	*
*	VSHMETH1(	0)=YES	VSHM (	0)=	1.0000	*	