

PAGE 5

*	NRUNA	(	0)=	3.0000	NRUN	(	0)=	2.0000	*
*	OPTION	(	1)=	1.0000	NSW	(	0)=	2.0000	*
*	PLOTBUCK	(	0)=YES		OPTION	(	2)=	1.0000	*
*	PLOTREF	(	0)=M		PLOTPICK	(	0)=YES		*
*	RESPLOT	(	0)=NO		PLTSCALE	(	0)=	500.0000	*
*	RHOGLM	(	1)=	2.7100	RHOF	(	1)=	1.0000	*
*	RM	(	0)=	0.0	RHOGSD	(	1)=	2.6500	*
*	RMF	(	0)=	0.0	RMDAT	(	0)=	0.0	*
*	RMF	(	2)=	0.4820	RMF	(	1)=	0.5000	*
*	RMF	(	4)=		RMF	(	3)=		*
*	RMF	(	6)=		RMF	(	5)=		*
*	RMFTMP	(	2)=	72.0000	RMFTMP	(	1)=	72.0000	*
*	RMFTMP	(	4)=		RMFTMP	(	3)=		*
*	RMFTMP	(	6)=		RMFTMP	(	5)=		*
*	RMTEMP	(	0)=	0.0	RMFTMP	(	0)=	0.0	*
*	STDOFF	(	1)=	1.5000	RWPLOT	(	0)=YES		*
*	STDOFFA	(	1)=	0.0	STDOFF	(	2)=	1.5000	*
*	SURFTMP	(	0)=	70.0000	STDOFFA	(	2)=	0.0	*
*	SWCUT1	(	0)=	50.0000	SW	(	0)=	3.0000	*
*	SWMETH1	(	0)=YES		SWCUT2	(	0)=	80.0000	*
*	SWMETH3	(	0)=NO		SWMETH2	(	0)=NO		*
*	TEMPREF	(	0)=F		TAPE	(	0)=	111.0000	*
*	TOPRUN	(	1)=	6100.0000	TF	(	0)=	11131.0000	*
*	TOPRUN	(	3)=		TOPRUN	(	2)=	8807.0000	*
*	TOPRUN	(	5)=		TOPRUN	(	4)=		*
*	TRACE	(	0)=NO		TOPRUN	(	6)=		*
*	VSHGRMAX	(	1)=	90.0000	USEZEROS	(	0)=NO		*