

PAGE 5

*	PLOTBUCK(	0)=YES							
*	PLOTREF (	0)=M				PLOTPICK(	0)=YES		*
*	PLTSCALE(	0)=	500.0000			PLOTRES (	0)=NO		*
*	RHOF (	1)=	1.0000			RESPLOT (	0)=NO		*
*	RHOGSD (	1)=	2.6500			RHOGLM (	1)=	2.7100	*
*	RMDAT (	0)=	74033.0000			RM (	0)=	0.7800	*
*	RMF (	1)=	0.5900			RMF (	0)=	0.5900	*
*	RMF (	3)=				RMF (	2)=		*
*	RMF (	5)=				RMF (	4)=		*
*	RMFTEMP (	1)=	75.0000			RMF (	6)=		*
*	RMFTEMP (	3)=				RMFTEMP (	2)=		*
*	RMFTEMP (	5)=				RMFTEMP (	4)=		*
*	RMFTMP (	0)=	75.0000			RMFTEMP (	6)=		*
*	RWPLLOT (	0)=YES				RMTEMP (	0)=	78.0000	*
*	STDOFFA (	1)=	0.0			STDOFF (	1)=	1.5000	*
*	SW (	0)=	1.0000			SURFTEMP(	0)=	70.0000	*
*	SWCUT2 (	0)=	80.0000			SWCUT1 (	0)=	50.0000	*
*	SWMETH2 (	0)=NO				SWMETH1 (	0)=NO		*
*	TAPE (	0)=	128.0000			SWMETH3 (	0)=YES		*
*	TF (	0)=	12831.0000			TEMPREF (	0)=F		*
*	TOPRUN (	2)=				TOPRUN (	1)=	4600.0000	*
*	TOPRUN (	4)=				TOPRUN (	3)=		*
*	TOPRUN (	6)=				TOPRUN (	5)=		*
*	USEZEROS(	0)=NO				TRACE (	0)=NO		*
*	VSHGRMIN(	1)=	1.0000			VSHGRMAX(	1)=	80.0000	*
*	VSHMETH1(	0)=YES				VSHM (	0)=	1.0000	*
*	VSHMETH3(	0)=NO				VSHMETH2(	0)=NO		*
						VSHMETH4(	0)=NO		*