

PAGE 11

*	NRUN	(	0)=	1.0000	NINT	(	0)=	2.0000	*
*	NSW	(	0)=	2.0000	NRUNA	(	0)=	2.0000	*
*	PLOTBUCK	(	0)=YES		OPTION	(	1)=	1.0000	*
*	PLOTREF	(	0)=M		PLOTPICK	(	0)=YES		*
*	RESPLOT	(	0)=NO		PLTSCALE	(	0)=	500.0000	*
*	RHOF	(	2)=	1.0000	RHOF	(	1)=	1.0000	*
*	RHOGLM	(	2)=	2.7100	RHOGLM	(	1)=	2.7100	*
*	RHOGSD	(	2)=	2.6500	RHOGSD	(	1)=	2.6500	*
*	RMDAT	(	0)=	0.0	RM	(	0)=	0.0	*
*	RMF	(	1)=	0.8380	RMF	(	0)=	0.0	*
*	RMF	(	3)=		RMF	(	2)=		*
*	RMF	(	5)=		RMF	(	4)=		*
*	RMFTMP	(	1)=	16.0000	RMF	(	6)=		*
*	RMFTMP	(	3)=		RMFTMP	(	2)=		*
*	RMFTMP	(	5)=		RMFTMP	(	4)=		*
*	RMFTMP	(	0)=	0.0	RMFTMP	(	6)=		*
*	RWPLT	(	0)=NO		RMTEMP	(	0)=	0.0	*
*	STDOFFA	(	1)=	0.0	STDOFF	(	1)=	1.5000	*
*	SW	(	0)=	1.0000	SURFTMP	(	0)=	70.0000	*
*	SWCUT2	(	0)=	80.0000	SWCUT1	(	0)=	50.0000	*
*	SWMETH2	(	0)=NO		SWMETH1	(	0)=NO		*
*	TAPE	(	0)=	134.0000	SWMETH3	(	0)=YES		*
*	TF	(	0)=	13431.0000	TEMPREF	(	0)=M		*
*	TOPRUN	(	2)=		TOPRUN	(	1)=	5415.0000	*
*	TOPRUN	(	4)=		TOPRUN	(	3)=		*
*	TOPRUN	(	6)=		TOPRUN	(	5)=		*
*	USEZEROS	(	0)=NO		TRACE	(	0)=NO		*