

2090.4001	.3253	.2422	.2417	
Averages	.3079	.3328	.2461	
Interval Thickness =		.3000	Porosity Thickness =	.0738
2540.5000	.1290	.4961	.2200	
Averages	.1290	.4961	.2200	
Interval Thickness =		.0999	Porosity Thickness =	.0220
2622.6001	.3953	.4401	.2450	
2622.7000	.3349	.4626	.2599	
2622.8000	.3005	.4809	.2683	
2622.9001	.2841	.4928	.2722	
Averages	.3287	.4691	.2613	
Interval Thickness =		.4001	Porosity Thickness =	.1046
2631.5000	.2980	.4810	.1612	
Averages	.2980	.4810	.1612	
Interval Thickness =		.0999	Porosity Thickness =	.0161
2658.0000	.3823	.3690	.2157	
2658.1001	.3631	.3928	.2204	
2658.2000	.3408	.4063	.2259	
2658.3000	.3160	.4105	.2320	
2658.4001	.3074	.4115	.2341	
Averages	.3419	.3980	.2256	
Interval Thickness =		.5000	Porosity Thickness =	.1128