

Director

362064 p 8/2

Daily Report 10th November

Deerwood 1

Dpdk 8029'

Trustee off again & trying
to recover string, so far unsuccessfully.

Geology - remains the same (12)
Heavy sandstone with some porosity
& permeability - no shows.

meeting today with Esso to determine
future program.

J. D